



CHASSIS MOUNTING HOLE
THICKNESS:0.8~1.8

PART NO.	A	B
LCMM-8		
LCMM-18		

NOTE:D