



HOLE IN FAN $\phi 3.1 \sim \phi 3.3 \text{mm}$
 FAN CHASSIS THICKNESS $3.9 \sim 4.6 \text{mm}$

新公差

NOTE:N