



MOUNTING HOLE  
CHASSIS THICKNESS 1.6

PART NO.	A	B	C
CAPI-18	18.0	18.5	10.0