



MOUNTING HOLE $\phi 4.8$
THICKNESS:E

PART NO.	A	B	E
MBW-17	18.5	17.5	2.54~15.2
MBW-23	21.5	20.5	4.0~25.0