



Shrinking is normal status



PART NO.	A	B	C	D
HANU-77	32.0	29.3	23.0	6.3